

Output from flashing Xperia 10 III with Windows 10 computer

Sailfish OS: 4.4.0.58

This is a Windows flashing script for Sony Xperia 10 III device.

Power on the device in fastboot mode, by doing the following:

1. Turn off your Xperia.
2. Connect one end of a USB cable to your PC.
3. While holding the volume up button pressed, connect the other end of the USB cable to your Xperia.
4. After this you should see the blue LED lit on Xperia, and it will be ready for flashing

Press any key to continue . . .

Verifying MD5 checksums...

MD5SUM 'ed5a809dc0024d83cbab4fb9933d598d' match for file 'AdbWinApi.dll'.
MD5SUM '0e24119daf1909e398fa1850b6112077' match for file 'AdbWinUsbApi.dll'.
MD5SUM 'b84cf5d3dc1747787281ff0d2c31d2ae' match for file 'fastboot.exe'.
MD5SUM '81afclee3e58b7bca34a3e39d51ee384' match for file 'flash-on-windows.bat'.

Searching for a compatible device...

The device is unlocked for the flashing process. Continuing..

Found 'SW_binaries_for_Xperia_Android_11_4.19_v9a_lena.img' that will be used as vendor image. Continuing..

MD5SUM '164eea9acab75774f926c56625969e06' match for file 'hybris-boot.img'.

C:\FLASH\XPERIA\Sailfish_OS-Jolla-4.4.0.58-xqbt52-1.0.0.114>fastboot.exe -s HQ615S5999 flash boot_a hybris-boot.img

Sending 'boot_a' (25788 KB) OKAY [0.585s]

Writing 'boot_a' OKAY [0.132s]

Finished. Total time: 0.733s

MD5SUM '164eea9acab75774f926c56625969e06' match for file 'hybris-boot.img'.

C:\FLASH\XPERIA\Sailfish_OS-Jolla-4.4.0.58-xqbt52-1.0.0.114>fastboot.exe -s HQ615S5999 flash boot_b hybris-boot.img

Sending 'boot_b' (25788 KB) OKAY [0.587s]

Writing 'boot_b' OKAY [0.120s]

Finished. Total time: 0.707s

MD5SUM 'bc3291903dded551122b1133895eea89' match for file 'sailfish.img001'.

C:\FLASH\XPERIA\Sailfish_OS-Jolla-4.4.0.58-xqbt52-1.0.0.114>fastboot.exe -s HQ615S5999 flash userdata sailfish.img001

Sending sparse 'userdata' 1/3 (785151 KB) OKAY [17.968s]

Writing 'userdata' OKAY [14.861s]

Sending sparse 'userdata' 2/3 (775847 KB) OKAY [17.920s]

Writing 'userdata' OKAY [15.832s]

Sending sparse 'userdata' 3/3 (356416 KB) OKAY [8.375s]

Writing 'userdata' OKAY [7.730s]

Finished. Total time: 86.374s

MD5SUM '92a4251c79d83ff45eeb5ac35aa2453f' match for file 'dtbo.img'.

C:\FLASH\XPERIA\Sailfish_OS-Jolla-4.4.0.58-xqbt52-1.0.0.114>fastboot.exe -s HQ615S5999 flash dtbo_a dtbo.img

Sending 'dtbo_a' (238 KB) OKAY [0.016s]

Writing 'dtbo_a' OKAY [0.000s]

Finished. Total time: 0.047s

MD5SUM '92a4251c79d83ff45eeb5ac35aa2453f' match for file 'dtbo.img'.

C:\FLASH\XPERIA\Sailfish_OS-Jolla-4.4.0.58-xqbt52-1.0.0.114>fastboot.exe -s HQ615S5999 flash dtbo_b dtbo.img

Sending 'dtbo_b' (238 KB) OKAY [0.016s]

Writing 'dtbo_b' OKAY [0.000s]

Finished. Total time: 0.047s

C:\FLASH\XPERIA\Sailfish_OS-Jolla-4.4.0.58-xqbt52-1.0.0.114>fastboot.exe -s HQ615S5999 flash oem_a

SW_binaries_for_Xperia_Android_11_4.19_v9a_lena.img

Sending 'oem_a' (343636 KB) OKAY [7.606s]

Writing 'oem_a' OKAY [0.000s]

Finished. Total time: 7.960s

Flashing completed.

Remove the USB cable and bootup the device by pressing powerkey.

Press any key to continue . . .